Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
11	17245290	(@ad<"19981211") aqnd 438/111,123,617.ccls. and wire\$3 and (press\$3 or clamp\$3)	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 12:15
L2	322	(@ad<"19981211") and 438/111, 123,617.ccls. and wire\$3 and (press\$3 or clamp\$3)	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 13:22
L3	307	L2 and (lead or leads)	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 12:16
L4	115	L3 and ((chip or die) near (mount or pad or paddle))	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 12:38
L5	21427	((chip or die) near (mount or pad or paddle))	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 12:39
L6	95	L5 and ((tab or projection or projecting) near (mount or pad or paddle)) and (@ad<"19981211")	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 13:20
L7	90	L6 not L4	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 12:40
L8	18	L7 and wire\$3 and (press\$3 or clamp\$3)	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 12:47
L9	5562	(chip or die) and ((tab or projection or projecting) with(clamp or clamping or press or pressing)) and (@ad<"19981211")	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 12:46

L10	5562	(chip or die) and ((tab or projection or projecting) with (clamp or clamping or press or pressing)) and (@ad<"19981211")	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 12:46
L11	40	L10 and ((tab or projection or projecting) near (mount or pad or paddle))	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 13:18
L12	13	L11 and wire\$3 and (press\$3 or clamp\$3)	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 12:47
L13	13	L11 and wire\$3	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 12:47
L14	14	L11 and wir\$3	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 12:48
L15	19	L7 and wir\$3 and (press\$3 or clamp\$3)	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 12:47
L16	1	L15 not L8	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 12:47
L17	5	wirebonder and ((tab or projection or projecting) near (mount or pad or paddle))	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 13:18
L18	658	(@ad<"19981211") and 257/666, 784.ccls. and wir\$3 and (press\$3 or clamp\$3)	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 13:18
L19	7	L18 and ((tab or projection or projecting) near (mount or pad or paddle)) and (@ad<"19981211")	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 13:23

L20	6	(@ad<"19981211") and 438/for. 366.ccls. and wire\$3 and (press\$3 or clamp\$3)	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 13:22
L21	19	(@ad<"19981211") and 438/for. 377.ccls. and wire\$3 and (press\$3 or clamp\$3)	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 13:22
L22	0	L21 and ((tab or projection or projecting) near (mount or pad or paddle)) and (@ad<"19981211")	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/16 13:23